


PRESSURE RESISTANCE AS A FUNCTION OF TEMPERATURE



(DO NOT EXCEED CURVE VALUES)

Using a steel ball valve below -20°C please contact the factory.